

## Flush Mount LED Strips

Amber

DNL.00.10000.A Instructions Rev:01

### PLEASE READ BEFORE INSTALLING

TWISTED THROTTLE products should be installed by a qualified, experienced motorcycle technician. If you are unsure of your ability to properly install a product, please have the product installed by your local motorcycle dealer. TWISTED THROTTLE takes no responsibility for damages caused by improper installation.


All screws, bolts, and nuts, including all replacement hardware provided by TWISTED THROTTLE should be tightened to the torque specified in the OEM maintenance manual for your motorcycle. If no torque specifications are provided in the OEM maintenance manual, the following torques may be used:

M5.....	3.5 ft-lbs (5 Nm)
M6.....	7 ft-lbs (9.6 Nm)
M8.....	13 ft-lbs (18 Nm)

All screws, bolts, and nuts should be checked after driving the first 30 miles (50 km) to ensure that all are tightened to the proper torque.

Medium strength liquid thread-locker (i.e., "Loctite") should be used to secure all screws, bolts, and nuts.

Distributed by:	
Twisted Throttle LLC 570 Nooseneck Hill Rd Exeter, RI 02822	phone: 855-255-5550 fax: 401.223.6955 www.twistedthrottle.com




### Instructions

**1**  
LED Light Strip  
  
Amber  
Qty.....2

**2**  
Posi-Tap Connector  
  
EX-130R  
Qty.....4

#### Option 1 (Turn Signals)


Note: This drawing is not to scale. Components are enlarged for illustrative purposes only.



**Option One:** Locate the negative and positive leads for your right hand turn signal and use a Posi-tap to connect the leads from the LED strip. Repeat these steps with the left hand turn signal.

#### Option 2 (Running Lights)

Note: This drawing is not to scale. Components are enlarged for illustrative purposes only.



**Option Two:** Locate a switched power source and a ground, then use a Posi-tap to connect the leads from the LED strips.